



Docket No.: 217713US90

OBLON
SPIVAK
McCLELLAND
MAIER
&
NEUSTADT
P.C.

ATTORNEYS AT LAW

COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313

RE: U.S. Patent No.: 6,713,844 B2

Issued Date: March 30, 2004

Serial No.: 10/026,639

Inventors: Jun TATSUTA, et al.

Title: SEMICONDUCTOR-CHIP MOUNTING SUBSTRATE
HAVING AT LEAST ONE PROJECTION THEREON
AND A PRESSURE HOLDING MEANS

Group Art Unit: 2827

Examiner: LOURDES C. CRUZ

Certificate
JUL 30 2004
of Correction

SIR:

Attached hereto for filing are the following papers:

REQUEST FOR CERTIFICATE OF CORRECTION


CERTIFICATE OF CORRECTION FORM PTO 1050 (IN DUPLICATE)

Our check in the amount of **\$0.00** is attached covering any required fees. In the event any variance exists between the amount enclosed and the Patent Office charges for filing the above-noted documents, including any fees required under 37 C.F.R. 1.136 for any necessary Extension of Time to make the filing of the attached documents timely, please charge or credit the difference to our Deposit Account No. 15-0030. Further, if these papers are not considered timely filed, then a petition is hereby made under 37 C.F.R. 1.136 for the necessary extension of time. A duplicate copy of this sheet is enclosed.

Respectfully submitted,

BEST AVAILABLE COPY

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.


Masayasu Mori

Registration No. 47,301

Customer Number

22850

(703) 413-3000 (phone)

(703) 413-2220 (fax)

I:\ATTY\PH21s\217713\217713 COC PTO CV.DOC

Philip J. Hoffmann
Registration No. 46,340

Docket No: 217713US90



IN THE UNITED STATES PATENT & TRADEMARK OFFICE

IN RE APPLICATION OF : GROUP ART UNIT: 2827
JUN TATSUTA, ET AL. : ALLOWED: SEPTEMBER 25, 2003
SERIAL NO: 10/026,639 : EXAMINER: LOURDES C. CRUZ
FILED: DECEMBER 27, 2001 : PATENT NO. 6,713,844 B2
FOR: SEMICONDUCTOR-CHIP : ISSUED: MARCH 30, 2004
MOUNTING SUBSTRATE
HAVING AT LEAST ONE
PROJECTION THEREON AND
A PRESSURE HOLDING MEANS

REQUEST FOR CERTIFICATE OF CORRECTION

COMMISSIONER FOR PATENTS
ALEXANDRIA, VIRGINIA 22313

SIR:

The following is a request for a Certificate of Correction in Serial Number 10/026,639,
now Patent Number 6,713,844.

In accordance with the provisions of Rule 1.322 of the Rules of Practice, which
implement 35 U.S.C. §254, the Patent Office is respectfully requested to issue a Certificate of
Correction in the above-identified patent.

In light of the fact that the errors were the fault of the PTO, no fees are required. The
errors are minor and their correction will not entail re-examination or constitute new matter. The
requested corrections are listed on Form PTO 1050.

BEST AVAILABLE COPY

Customer Number

22850

(703) 413-3000
Fax No. (703) 413-2220
GJM/kad

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND,
MAIER & NEUSTADT, P.C.

Masayasu Mori
Registration No: 47,301
Attorney of Record

Philip J. Hoffmann
Registration No: 46,340

AUG 03 2004

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,713,844 B2
DATED: Mar. 30, 2004
INVENTOR(S): Tatsuta et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5, Line 40, change "this sold state" to --this solid state--.

Column 11, Line 12, change "the conductive patter" to -- the conductive pattern --.

Mailing address of sender:

Patent No. 6,713,844 *B2*

Customer Number

22850

No. of add'l copies
(@ .30 per page)

Tel. (703) 413-3000
Fax. (703) 413-2220
(OSMMN 03/02)



BEST AVAILABLE COPY

AUG 03 2004